

K60XV MANUAL ERRATA

Rev. B-3, December 15, 2013

PLEASE MAKE THE FOLLOWING CHANGES TO THE MANUAL BEFORE PROCEEDING TO ENSURE THAT THE K60XV FUNCTIONS CORRECTLY

1. **Page 3, Parts Inventory, Ref D1-D2:** Change the description to read “Diode 1N4148”. Change the part number to “E560002”.
2. **Page 3, Parts Inventory, Ref RF-D19, RF-D20:** Add MV209 to the description so it reads “Diode, varactor, MV2109 or MV209”
3. **Page 4, add the following step after the second checkbox step:**
 - Install diodes D1 and D2 (1N4148). Orient the banded end (cathode) of each diode as indicated by its component outline.
4. **Page 4: Last checkbox step, add:** Do not trim the relay pins.
5. **Page 5:** Delete the note at the bottom of the page. It no longer applies.
6. **Page 6:** Delete the first, second and third checkbox steps (the SMT1B board is no longer used).
7. **Page 8, last step:** Change the second line to read “(MV2109 or MV209)”.
8. **Page 20:** On the schematic diagram, update the upper right corner with the changes shown below around D1 and D1:

